

	National Aeronautical Laboratory	Documentation Sheet	Document Classification Restricted
Title	: Investigation of Damaged Components of Chetak Helicopter Z-1418	Document No.	PD MT 8657
Author(s)	: S.Radhakrishnan, R.V.Krishnan and V.Ramachandran	Contents 18 pages	incl. 25 figures
Division	: Materials Science	No. of copies:	12
External participation	:	NAL Project No.	MT-9-861, MT-1-167
Sponsor	: Aeronautics R & D Board	Sponsor's Project No.	Aero/RD-134/100/10/
Approval	: V.Ramachandran	84-85/394	
Remarks	:	26	
Keywords	: Chetak helicopter, Spacing cables, Pitch control rods, Drag dampers, Vertical control rods, Free wheel assembly, Main gear box, Tensile overload failure		
Abstract	:	The report describes the investigation of damaged components retrieved from the wreckage of a Chetak helicopter which was involved in an accident.	